


ALL GLUED AND NAILED

REPAIR DETAIL FOR HOLE IN WEB NEAR BEARING

NOTE:
 DAMAGE TO I-JOIST FLANGE AND/OR WEB CAN CAUSE FAILURE OF FLOOR SYSTEM. SPAN, SPACING AND LOADING AS WELL AS EXTENT AND LOCATION OF DAMAGE ALL AFFECT THE REPAIR REQUIRED.
 EACH CASE SHALL BE REVIEWED.



TYPICAL REPAIR DETAIL "B"

P3 BY EACOM
 TYPICAL REPAIR DETAILS