

Peace of mind underfoot™


Barrette Structural Inc.

545, rang St-Malo Trois-Rivières, Québec (Canada) G8V 0A8 1 800 567-8644


www.openjoisttriforce.com

TYPICAL REPAIR METHOD FOR A NOTCHED 2X4 TOP CHORD, WITHOUT CUTTING THE OSB PANEL

SITUATION BEFORE REPAIR



SITUATION AFTER REPAIR



*PL PREMIUM GLUE ** Plywood - at least $\frac{1}{2}$ " 4 ply ($\frac{15}{32}$ ") or better

RTF-009-18

IMPORTANT NOTICES

This detail drawing is valid for uniform residential loads.

For other types of loads, contact the manufacturer.

Check out the www.openjoisttriforce.com website for the latest updates.







